

Oil Field Environmental Incident Summary

Incident: 20140117072218 **Date/Time of Notice:** 01/17/2014 07:15

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: SAFELY USA 5-8H

Field Name: FOREMAN BUTTE

Well File #: 25660

Date Incident: 1/16/2014 **Time Incident:** 10:00

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 102

Sec: 32

Qtr:

Location Description: Oil misted off location to the West going across country road, into a field about 100 yards on top of snow.

Submitted By: Mike Haase

Received By:

Contact Person: Mike Haase
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Miles

Distance Nearest Water Well: 2 Miles

Type of Incident: Treater Popoff

Release Contained in Dike: No

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	barrels	1	barrels	1	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/24/2016

Clean Up Concluded: 1/30/2014

Risk Evaluation:

None

Areal Extent:

400 yards

Potential Environmental Impacts:

None

Action Taken or Planned:

Scooped up the snow and put it in the flare pit. Steam cleaned the treater and tanks.

Wastes Disposal Location: Flare pit. When the snow melts we can suck it out and take it to a disposal

Agencies Involved:

Updates

Date: 1/21/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release sprayed off location. Followup is necessary.

Date: 1/30/2014 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

When I arrived at the site, the temperature was 6°F, with a wind from the northwest 15 miles per hour. I walked around the well pad and could not see any misting impact to areas around the pad. The tanks are located on the west side of pad; the treater is east of the tanks. This is a new pad; identification signs have not been installed. The area directly around the pad does not have vegetation established. I could not see any misting on road or near it. I do not see any other issues at this time. No follow-up inspection is required at this time.